E1/4 Corner Sec 19-101-16

Appears a cut was made at this location for Twp road const. found no evidence of PLS Corner or perpetuation of. set 5/8" ϕ iron on straight line between sec corners at the midpoint

on ℄ N-S Road
10' N. of ℄ FLD Drive ✓
IN Line with fe. E.
S. End 12" CMP SW 34.0
N. End 12" CMP ✓ 26.5

5/9/05 Fd Capped 5/8 - Set CIM

