✓

E 1/4 Cor - Sec 10-102-15

Bk 294, p 54

Dug hole at ℄ Twp Road N-S in line with fences E-W. Found no evidence of PLS corner.

Appears to have been a road cut here.

Set CIM at midpoint of N-S line from NE Cor - SEC. 10 to SE cor - Sec. 10

