N 1/4 COR SEC 10-102-17

DEC 2004

JHS CREW FOUND NO EVIDENCE OF PLS COR @ THIS LOCATION. TIED IN EXISTING FENCE & FLD DIV LINES NEAR THIS LOCATION & FOUND THAT THEIR LOCATIONS FIT WITH THE COR BEING AT THE MID POINT OF A STRAIGHT LINE BETWEEN SEC CORS USED COMPUTED POS. FOR THIS LOCATION

October 2012

JHS set 5/8" rebar at midpoint of of a straight line between Sec. Corners on fenceline running East-west. Set Steel post 1' North of Corner.

