NE Cor Sec 16 - 103 - 14

2002 Searched area and found No Evidence of original PLS Corner.

Set 5/8ø capped 13807 at location of rotted Wood Corner Fence Post in line with Fence remains West and South and Field Division East.

9-16-02

CPV
GKB

80°

50

