E¼ Cor. Sec. 36-104-15
Cert. Filed 6-30-93 by JHS
SEE BK. 384 pg. 42

1993 JHS CREW SEARCHED AREA AND FOUND NO EVIDENCE of Corig ORIGNAL COR. WOULD HAVE BEEN DESTROYED DURING DITCH CONST, THEREFORE WE SAT ⅝"ø x 16" IRON ON STRAIGHT LINE AT THE spit BETWEEN NE AND SE CORS. of SEC. which ALSO PLACED COR IN LINE with OLD FENCE LINE Running EAST.

7-22-97 Reset + Retied

7-25-06 FOUND CIM & SHOT W/GPS.

2-4-94 CLEAR 10°

DRR HLS (6)

NE COR. SEC. 36-104-15

CULT

CULT

NO. 8

2649.69'

"NOTE"

COR. 20'± South of Xing

OPEN Ditch

SE cor Box culv

TREES

OPEN Ditch

SW cor Box culv.

20'±

A

B

C

100'

spklw tk yeld post

⅝" IRONS ON Straight LINE ON Ditch SHLD.

A 46.51

B 47.95

C 57.98

CULT

CULT

CSAH 8

2649.69'

N

SE COR. SEC. 36-104-15