2-18-00 Cloudy 30° HLS

36

W¼ cor SEC. 28-101-14

8-29-80 THS CREW LOCATED CORNER
FOUND BRASS CAPPED PIPE
RLS 4423
SEE BOOK 170 - pg 56

NEED TIES.

2006 THS CREW FOUND 2" PIPE W/CORK INSIDE
BRASS CAP MISSING?

