N 1/4 cor 8-103-17

1938± Co Road Plan shows Sec line South of ℄, but shows no evidence of 1/4 cor. NE & NW cor of Sec were dug at this time.

Aug. 1998 Yaggy field crew used ℄ of Co Rd & fence lines N & S for cor.

Feb 1999 Searched area w/ locator & found nothing. Corner evidence presumed to be destroyed during road construction. County Highway Dept. used lost position. Lost position agrees with occupation lines in Sections 5 & 8. Accepted lost position as best evidence of orig. PLS corner.

2-18-99 SJT, JRJ

65

