Cert. Filed 8-95 by JHS

SE cor Sec 15-101-15

(North) A | (West) B

"ϕ Stone point top 33.87 | 36.74

2' Down below old Roadbed

Exc. Co. Backhoe & Found nothing. Used S1/4 cor & 1/16th Fence to double over dist. to SE cor. Set CIM on ℄ 2651.0 E of S1/4 cor.

HLS 0ER

4-24-00 Corner destroyed, reset

SEE Book 464 pg 38



9-7-94 SJT, JPA

21

