5-4-06 Cloudy 55° HLS ELM

SE COR SEC. 19-101-15

NO INFORMATION FOUND in MOWER Co. RECORDS

5-4-06 JHS CREW dug by HAND AND UNCOVERED twisted STEEL ROD.

JHS CREW DUG CORNER with RAY TUCKER BACKHOE. UNCOVERED ROD, REMOVED ROD AND CONTINUED DIGGING to 5'± AND FOUND NO OTHER EVIDENCE of PLS CORNER. RESET ROD AS FOUND 2'± BELOW ROAD SURFACE. SET 5/8" X 16" IRON with CAST IRON MON. OVER ROD FOUND, 60'± BELOW RD SURFACE

