SW CORNER SEC. 2-103-15

NO INFORMATION FOUND
IN MOWER CO. RECORDS

JHS CREW dug with
RAY TUCKER BACKHOE
UNCOVERED ½" IRON 40± DEEP
REMOVED IRON AND
CONTINUED DIGGING, FOUND
NO OTHER EVIDENCE of
PLS CORNER.
REPLACED ½" IRON
AS FOUND AND SET
⅝" X 16" IRON with
CAST IRON MON OVER
½" IRON FOUND
60± BELOW RD
SURFACE

8-04-06 HLS 31
Cloudy 80° MDH

