Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E 1/4 Corner of Section 30, Township 101N Range 14W, 5th P.M.

STATE OF MINNESOTA, County of MOWER

At the corner location shown on the sketch

☐ On 08/07/1997 (DATE) found a 5/8"X2' IRON

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 08/07/1997 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



SE NE
SEC 30–T101N–R14W
CULTIVATED

SW NW
SEC 29–T101N–R14W
CULTIVATED

SPK&W IN TOP FC POST

SPK&W IN TOP FC POST

43.6'

41.25'

33.45'

TWP. ROAD

SPK&W IN TOP FC POST

NE SE
SEC 30–T101N–R14W
CULTIVATED

NW SW
SEC 29–T101N–R14W
CULTIVATED

JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

BOOK 96 PAGE 285

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

SIGNATURE _____ DATE 9-9-97

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 2 P .M. on the 10 day of Sept A.D., 1997

COUNTY RECORDER Charles Enger

By Susan M. Davis, Deputy

DOCUMENT NO. 455997

M.H.D. FORM NO. 2105

Book 96 Misc Page 285

E 1/4 Cor SEC 30-101-14

This corner was originally established by Deputy Surveyor John Taylor of the U.S. General Land Office in 1853. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder
Tucker Land Surveying

No record of this corner was obtained from the above mentioned offices.

1997 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, dug with the county backhoe at the CL of township road E-W at location determined by D.N.R. personnel from a recent traverse they had done in section 29. Located a 5/8"x2' iron 0.2' below road surface. Continued digging and found no other evidence of original PLS corner. Reset 5/8" iron and placed a cast iron monument above iron found.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc. and D.N.R.