Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E1/4 Corner of Section 14, Township 101N Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 6-5-93 (DATE) found a NO EVIDENCE

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-5-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 6-14-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 2 P.M. on the 23 day of June A.D., 19 93

COUNTY RECORDER Amanda Conger

By Marlene Martin, Deputy

DOCUMENT NO. 421677

Bk 80 Misc. p. 6

M.H.D. FORM NO. 2105

BOOK 80 PAGE 6

STATEMENT OF EVIDENCE

E 1/4 cor Sec 14-101-16

This corner was originally established by Deputy Surveyors Charles Phipps and Edward Fitzpatrick of the U.S. General Land Office in 1854. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of the perpetuation of the original public land survey corner.

1889 Clausen, Mower County Surveyor, notes indicate a government post at this corner which was 40.34 chains north of the southeast corner of Section 14-101-16.

1958 Mower County Highway Department Book A and Road Plans for County State Aid Highway No. 18 indicate a concrete monument inplace.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, found no evidence of this corner. Concrete monument inplace in 1958 was destroyed by ditch construction. Therefore we set a cast iron monument using a straight line from the northeast corner of Section 14-101-16 and the southeast corner of said Section 14 and also in line with old east-west fence lines, as shown on the County Road Plans. Cast iron monument set is four feet east of centerline which agrees with 1958 County Road Plans.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.