Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SW Corner of Section 36, Township 101N Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 6-5-93 (DATE) found a HARRISON CIM IMBEDDED IN A 6"ø CONC BASE

■ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-5-93 (DATE) placed a LEFT MONUMENT AS FOUND

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Mont Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 6-1893

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 4 P.M. on the 24 day of June A.D., 1993

COUNTY RECORDER Douglas Evans

By Marlene Martin, Deputy

DOCUMENT NO. 121722

By 80 Mon Rg. 123

M.H.D. FORM NO. 2105

BOOK 80 PAGE 123

STATEMENT OF EVIDENCE

SW cor Sec 36-101-16

This corner was originally established by Deputy Surveyor Andrew Talcott of the U.S. General Land Office in 1852. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of the perpetuation of the original public land survey corner.

1931 Mower County Highway Department Book 1 notes indicate a large pointed rock at this location.

1958 Mower County Highway Department Book 1 and the County Road Plans indicate a concrete monument inplace.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, searched area and found a Harrison cast iron monument inbedded in 6" diameter concrete base on the south shoulder of east-west Township Road No. T-48. The measured distance from the northwest corner of Section 36 to the southwest corner of Section 36 was within one foot more or less of the County State Aid Highway No. 18 road plan distance and also the centerline of County State Aid Highway No. 18 running north was on section line as according to said road plan. Therefore we accepted monument found as the perpetuation of the original public land survey corner and left the monument as found.

The monument found fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.