CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

CENTER QUARTER Corner of Section 6, Township 102N, Range 17W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 9-4-90 found 1/2" REBAR LYING HORIZONTAL (REMOVED DURING EXCAVATION)

☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)

On _____ placed NOTHING

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson — Signature
11-6-90 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof Engineer
☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the _____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

Center Quarter Corner Section 6, Township 102 North, Range 17 West, 5th P.M.

1972	County Highway Engineer's plans give no indication of monumentation.
September 4, 1990	Zenk Read Trygstad and Associates excavated with a backhoe through the bituminous pavement 1.8 feet North to 1.2 feet South of County Road 58 centerline by 2 feet East to 3 feet West of the fence line North by 3.7 feet deep and found a mangled 1/2" rebar just below the bituminous. The top of the bar was approximately 1.2 feet Northwest of the bottom. No exact location for the bar could be determined. No survey measurements were made to determine the position of the intersection of the quarter lines.

RJO/4967STMT