Index No. P20 "M"

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SE Corner of Section 18, Township 102N, Range 17W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 7-13-87 (DATE) found a 3/4" ø iron in line with fences north and east.

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 7-13-87 (DATE) placed a cast iron monument on road surface over iron found.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE 12-12-88 DATE

Registration No. 13807

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE
SE corner Section 18-102-17

This corner was originally established by Deputy Surveyor William I. Anderson of the US General Land Office in 1854. The government notes show this corner was marked with a wood post and the following bearing trees were marked:

10" Burr Oak	S 72° W	70 Links
9" Burr Oak	N 53° W	385 Links
16" Burr Oak	N 4° E	395 Links
17" Burr Oak	N 51° E	30 Links

The following were contacted for section corner information:

Mower County Engineering Department

No record of this corner was obtained from the Mower County Engineer Department or from the private records of Jones, Haugh & Smith Inc.

1987 Jones, Haugh & Smith crew dug with the Mower County backhoe on centerline of road tangents south and west in line with fence east and north and uncovered a 3/4" diameter iron one foot below ground surface. Continued digging and found no further evidence of public land survey corner.

The location of corner appears it would have been destroyed by township road construction. The position of iron found was in the easterly road ditch. Accepted iron found as best evidence of the original public land survey corner and set a cast iron monument.

For electronic survey data and analysis, contact firm of Jones, Haugh & Smith