CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

CENTER Corner of Section 16, Township 102N, Range 18W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 7-2-90 found A 5/8" REBAR

☐ left monument as-found, ☐ lowered monument, ☑ removed monument (explain)

On 7-9-90 placed A 1/2" PIPE IN PLACE OF 5/8" REBAR

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson — Signature
7-13-90 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof. Engineer
☐ County Surveyor ☐ County Engineer

Zenk·Read·Trygstad & ASSOCIATES, INC.
Engineers/Architects/Land Surveyors/Planners
Box 689, Albert Lea, MN 56007 507/373-0689

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the ____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

CENTER QUARTER CORNER SECTION 16, TOWNSHIP 102 NORTH, RANGE 18 WEST, 5TH P.M.

1933 — County Engineers Road Plans shows North South quarter line crossing at 132+00; 2654.5 feet from the East quarter corner of Section 17, but shows no monument inplace.

1967 — County Engineers Road Plans shows intersection of quarter lines at 2655.3 feet East of the East quarter corner of Section 17.

July 2, 1990 — Zenk Read Trygstad & Associates excavated with a backhoe 3 feet East to 7 feet West of the grass line South and from 1 foot North to 2 feet South of the road centerline by 5 feet deep being around the rebar. Nothing else was found.

Analysis of the record data gives no indication of the origin of the rebar and no survey was made to determine its agreement with the intersection of the Quarter lines. The pipe only replaces the rebar.