Index No. P 35 "G" P 108 "O"

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E1/4 Corner of Section 1, Township 103N Range 18W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On NOV. 1991 (DATE) found a 5/8"ø IRON OVER A 2.5" × 3/4" × 16" IRON OBJECT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On NOV. 1991 (DATE) placed a CAST IRON MONUMENT OVER 5/8"ø IRON

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE 4-30-93 DATE

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 3 P .M. on the 4 day of May A.D., 1993

COUNTY RECORDER Charlene Conger

By Marlene Martin, Deputy

DOCUMENT NO. 420482.

Bk 79 Misc Pg. 330

M.H.D. FORM NO. 2105

BOOK 79 PAGE 330

STATEMENT OF EVIDENCE

E 1/4 corner Section 1-103-18

This corner was originally established by Deputy Surveyor Elisha S. Norris of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench. The following tie was taken:

18" Burr Oak N 20 1/2° E 340 links (224.40 ft)

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1884 Clausen, Mower County Surveyor, found a government post at the E 1/4 of Section 1.

1991 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, Reg. No. 13807, dug with county backhoe and found a 5/8" diameter iron 0.5 feet deep over a 2 1/2" x 3/4" x 16" long iron object two feet deep. The monuments found agreed with the line fences running east and west. Therefore we set cast iron monument near road surface and above 5/8" diameter iron found.

The monument set fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 79 PAGE 331

Jones & Haugh