Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHWEST Corner of Section 31, Township 103 N, Range 17 W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 10/22/09 (DATE) found a BROKE OFF WOOD CORNER POST IN CONCRETE

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 5/19/11 (DATE) placed a 3/4" IRON PIPE IN CENTER OF WOOD POST

SKETCH OF REFERENCE TIES



NAD83 (1996 ADJUSTMENT)
MOWER COUNTY COORDINATES

N= 170450.700
E= 769839.213

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Peter W. Blethen — 5/11/12 (DATE)

Peter W. Blethen

Registration No. 17367

☒ Land surveyor, ☐ County Surveyor,

MISC.1013 PG.61
I:\PRIV\M32101475\CAD\CORNER CERTIFICATES.DWG

Statement of Evidence:

Northwest Corner Section 31, Township 103 North, Range 17 West

1854 In October, William L Anderson US deputy Surveyor surveyed and established all section corners, quarter section, and meander corners.

1974 Mower County ties sheet shows a pk nail in the top of a corner fence post.

2009 On October 22, a Bolton & Menk Inc survey crew survey serached for this corner. The survey crew found a corner fence post in concrete. The corner post had rottend and broken. The survey crew set an iron pipe monument in the portion of the post that still was inside the concrete.

2011 On May 19, Bolton & Menk Inc, survey crew revisited the corner and made new ties. The corner post seems to be in a reasonable location and the iron pipe is accepted as the corner.

A000597347

OFFICE OF COUNTY RECORDER
MOWER COUNTY MINNESOTA

I HEREBY CERTIFY THAT THE WITHIN
INSTRUMENT WAS FILED, AND/OR
RECORDED ON 05/17/2012 08:52AM

AS DOC #: A000597347
REC FEE: $46.00

JILL CORDES
COUNTY RECORDER

BY