Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 30, Township 102N, Range 17W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 8-7-85 (DATE) found a NO EVIDENCE OF CORNER

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 8-7-85 (DATE) placed a conc. nail & W. in bridge deck

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 12-12-88

Registration No. 13807

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE
NE corner Section 30-102-17

This corner was originally established by Deputy Surveyor William I. Anderson of the US General Land Office in 1854. The government notes show this corner was marked with a wood post and the following bearing trees were marked:

9" Burr Oak	N $15\frac{1}{2}^{o}$ W	238 Links
7" Burr Oak	N 55^{o} E	174 Links

The following were contacted for section corner information:

Mower County Highway Department

1985 Jones, Haugh & Smith crew found no evidence of public land survey corner or a perpetuation of. Appears corner was destroyed by rechanneling of creek and bridge construction. Therefore established position of corner using obliterated methods.

For electronic survey data and analysis, contact firm of Jones, Haugh & Smith