SE COR SEC 32

MOWER CO HAS NO RECORD OF A COR @ THIS LOCATION IN CO. ENG. OFFICE.

3-7-06 JAJ CREW VISITED THIS LOCATION & FOUND NO EVIDENCE OF P.L.S. COR

COMPUTED POS. FOR THIS COR @ MIDPOINT BETWEEN S 1/4 COR SEC 33 & S 1/4 COR SEC 32 IN EXISTING E-W FENCE LINE ON SO SIDE SEC 32 & 33

