4-14-06 HCS
Cloudy MLS 18
70°

Sth cor SEC. 34-102-15

No Information Found
in Mower Co. Records

JHS crew looked at
area, found plastic
culv. crossing road
cor. would have
been destroyed at
time of const.
Set cor. on straight
line to best fit to lines
Set 5/8" x 16" iron with
cap No. 13807
.60± Below Rd. Surface

