6-1-06 HLS
Cloudy 75° MDH 25

NE cor SEC-10-101-15

NO INFORMATION FOUND IN MONROE CO. RECORDS

JHS CREW dug with RAY TUCKER BACKHOE ON ℄ E-W Twp ROAD AND IN LINE with FIELD DIVISION South.

Dug 1.5' AND WAS into CLAY, ROAD AT this POINT WAS cut, so CORNER would HAVE BEEN DESTROYED, AT TIME of CONST.

SET CORNER USEing ℄ E-W Twp ROAD AND FIELD DIVISION South. SET 5/8" x 2' IRON with CAST IRON MON. OVER .20' BELOW ROAD SURFACE

