SE cor SEC. 2-101-15

NO INFORMATION FOUND IN MONTEREY CO. RECORD

THS CREW dug with NAY TUCKER BACKHOE AT LOCATION of SIGNAL from LOCATION.

UNCOVERED 3/4" X 14" IRON .40± BELOW ROAD SURFACE

REMOVED IRON AND dug BELOW, FOUND NO OTHER EVIDENCE of PLS COR.

RESET 3/4" IRON LOWER AND SET 5/8" X 16" IRON with CAST IRON MON. OVER. .60± BELOW Rd. SURFACE.

5-1-06 Cloudy 75° THS MOH 78

