E¼ cor SEC 26-101-15

No Information Found in Mower Co. Records

HLS crew dug with Ray Tucker Backhoe on 4 N-S Twp Rd and in line with Line Fence East. Dug Down to Clay and Found No Evidence of PLS Cor.

EJM Set corner on 4 Road and in line with fence from the E¼ corner of section 25-101-15 running west through center of section 25.

6/29/06 Set CIM SAT

6-7-06 Cloudy 85° HLS MDH 26

