E¼ cor SEC. 7 - 101-16

NO Information Found in Mower Co. Records

JHS crew located 4" steel post on E-W line fence and in line with Fld Division North. Found no other evidence of PLS corner. Accepted post as true corner and set 5/8" x 8" iron with cast iron mon on east side of post.

5.29-98 cloudy 80° JHS ELM

32

