6-2-05
Cloudy
75°

HLS
MHS

24

S 1/4 Cor Sec 5-101-16

No information found on Corner
in Mower Co. Corner Records

5/11/05 fd 5/8" ø Bent on ℄ of Road

JHS Crew Dug with Bobe Bros.
Backhoe, Uncovered Bent 5/8" ø
Removed 5/8" ø continued
Digging and Found No other
Evidence of PLS Corner.

Reused Point of Bent 5/8" ø
and Set 5/8" x 16" Iron with
Cast Iron Mon.

60± Below Rd Surface

