SW Cor Sec 15-101-16
Cert. Filed 5-6-91 by JHS
Dog W/ Co. backhoe
a 4' x 35' x 5' deep
hole for bridge
#2614 survey
and found no evidence
of PLS Corner or a
perpetuation of,
Using testimony of
mr Hanson farmer
owning all the land
around corner says
1950± road was
cartway N-S-W and
old fenke east, IN
1960± cart way W.
was removed and
Power line built 2 rods
North ± of old ℄
Power line E. was
constructed in
old fence which is
gone at present time
accepted ℄ N-S road
and power line East
as best evidence and
set CIM

4-22-91 DRR RMK 1 ✓

