N¼ cor SEC. 15 - 101 - 17

4-16-76 JHS CREW PLACED 5/8" ⌀ ℄ ROAD & IN LINE with FC NORTH.

SPK/W IN PP W. SIDE - NW 54.9

SPK/W IN PP - E. SIDE - NE 55.05

JHS CREW CHECKED for CORNER with LOCATION. COULDN'T LOCATE CORNER. RESET CORNER USING TIES - PLACED 5/8" X 8" IRON.

5-07-02 DUG with MOUNTED BACKHOE AT LOCATION of 5/8" ⌀ PLACED. DUG DOWN to VIRGIN SOIL AND FOUND NO EVIDENCES of PLS CORNER. REPLACED 5/8" ⌀ with CAST IRON MON OUTER . . 60± BELOW ROAD SURFACE

1-10-02
CLOUDY
35°
HLS
CPU

56

