Et4 cor SEC. 22-101-18

NO INFORMATION FOUND IN MOWER CO. CORNER RECORDS

JHS CREW FOUND OPEN DITCH CROSSING TWP. RD ON SECTION LINE. CORNER WOULD HAVE BEEN DESTROYED BY CONST. OF OPEN DITCH

SET COR. BY USEING LINE FENCE EAST @ EAST END of OPEN DITCH, EXTENDED EAST LINE FENCE WEST TO CENTER of N-S TWP ROAD.

SET 5/8" ø WITH CAST IRON MON. .60 ± BELOW SURFACE.

10-19-04
CLOUDY
60°
JHS
MHS

75

