SW Cor Sec 19-101-16

Found no evidence of PLS corner or a perpetuation of. set a 5/8" ø iron by double proportional parts E-W from Sec corners and Doubleing over from the south

> E. ℄ N-S road on ℄ E-W road
SPK & W PP NW 51.30
SPK & W PP NE 44.20
E END 24" CMP SE 28.60

SEE-Book 394 pg 73
4-14-98 HLS & MLG
SET CIM OURS 5/8" ø Found
cap 13807

3-25-88 DRR 52
Cloudy & windy RMK
40°

