E¼ cor SEC. 25 - 101 - 18

Cert. Filed by JHS 8-16-96

No Information Found in

Mower Co. Records

to Wobble in PT

DKST SE cor D 2969.85 Fd Cem

FS NE cor ∡ 180°00'00" D 2339.35 Fd Cem

FS E¼ cor 00°00'00" D 307.02

JHS Crew Dug with Mower Co.

Backhoe, on E of North - South

Twp Road & in line with Line

Fence East - Field Division West

Dug a 5'X12' Hole 3.5' Deep

to Virgin Soil and Found No

Evidence of PLS Corner.

Set corner on straight

Line Between SE cor & NE cor

Corner Fits E of Twp Road

& in line with Line Fence East

Field Division West.

Set ⅜" X 16" Iron with

Cast Iron Mon, No Below

Road Surface.

7-2-96 cloudy 80° HLS 42'

