NE Cor SEC. 25-101-18

Cert Filed by JHS 7-25-96

NO INFORMATION FOUND IN MOWER

Co. RECORDS.

5-12-00 RESET CORNER, SET CIM. HLS DHK

CORNER WAS DESTROYED ROAD

CONST.

JHS CREW Dug with MOWER Co.

BACKHOE, ON ℄ of TWP ROAD

NORTH-SOUTH & ℄ of TWP ROAD

EAST & WEST. UNCOVERED 6" SPK.

@ 1.5' DEEP, IN OLD ROAD BED.

Dug by HAND BELOW SPK, UNCOVERED

ROTTED WOOD STAKE 1' LONG.

CONTINUED DIGGING AND FOUND NO

OTHER EVIDENCE of PLS CORNER

ACCEPTED SPK & WOOD STAKE

AS TRUE CORNER.

SET 5/8" X 16" IRON with CASTIRON

MON IN PLACE of SPK & STAKE.

.40' BELOW ROAD SURFACE.

7-2-96 HLS

Cloudy

80°

43

