S ¼ cor SEC 7-102-14

No information in Mower Co. Records

JHS crew dug with Ray Tucker backhoe on ℄ Twp Road E-W and Field North and South.

Found no evidence of PLS cor.

Set cor. using ℄ E-W Twp Road and Field Division's North & South.

Set 5/8"x16" iron with cast iron mon. over 1.60+ Below Rd Surface.

4-4-06
Cloudy
50°

HLS
MLS

15

