N 1/4 Cor Sec 3 - 102 - 15

2002 JHS Crew Dug by hand at 4-way Fence Intersection. Found No Evidence of original PLS Corner.

Set 5/8" Ø Capped (8907) at 4-way Fence Intersection.

5-13-02
65°
Cloudy

CNV
GKB

32

