4-5-06
Cloudy
60

HLS
MLS

EXCOR SEC. 19-102-15

No Information Found
in Mower Co. Records

JHS CREW dug with
RAY TUCKER BACKHOE
AND UNCOVERED a 1"X36" Shaft
& Continued AND Found
STONE ON South SIDE of
Shaft.
Lowered Shaft AND SET
5/8" X16" Iron with Cast Iron
MON. OVER MON'S Found
.60± BELOW Rd. SURFACE

