4-10-06
CLEAR
HLS
MLS

61

S 1/4 COR SEC 25

MOWER CO 1971 ROAD GRADING PLAN SHOWS NO COR @ THIS LOCATION, & THAT COR WOULD HAVE BEEN IN A CUT SECTION WHICH WOULD HAVE DESTROYED ORIG PUBLIC LAND SURVEY COR. HOWEVER CO ROAD PLAN DID SHOW FENCE LINES N & SO. @ A DIST OF 2654.20' EAST OF SW COR OF SEC. DUE TO THIS LOC

SET @ 6609

PT. 6654

CHR. 6682

JHS CREW dug with RAY TUCKER BACKHOE, on ℄ of ROAD AND INCLINE with LINE South. At a dist. of 2654.20 EAST of SW COR.

UNCOVERED NO EVIDENCE of PLS COR, SET CORNER USEING ROAD PLAN.

SET 5/8" X 16" IRON with CASTIRON MON. OVER, 1.60± BELOW Road Surface

