8-1-96
CLEAR
80°

HLS
TRS

S¼ cor SEC. 30-102-16
Certified by JHS 5-8-97
No Information Found in
Mower Co. Records

to	SE cor SEC. 30	Fd CIM	
B/LST	SW cor SEC. 30	Fd CIM	
D	5152.90	Gov. 5227.20 = LESS 74.30	

2640 - 37.15 = 2602.85

JHS CREW with Mower Co.
BACKHOE · Gov. dist 5227.90,
Found 5152.90 FROM SE cor to
SW cor, Proportion dist, Dug
@ 2602.85 From SE cor on
Straight Line BETWEEN
SE & SW cor's. Point FALLS 5' South
of ℄ of ROAD. Dug a 3'x6'x5'
DEEP hole, Found NO EVIDENCE
of PLS CORNER.

SET CORNER @ Proportional
dist. 2602.85 From SE cor
ON Straight Line
SET 5/8" x 16" IRON with
CAP stamped MON.

SEC. 30-102-16

CULT

5/8" ∅ SOLID

5/8" ∅ SOLID

CSAH ∅

50'

5'

50' ∅

NO. 4

℄ of ROAD

SW COR CIM

2560.05

50'

2602.85

SE cor CIM

5/8" ∅ SOLID

SEC. 31-102-16

CULT