✓ (by whom = ?)

SE cor - Sec. 27-102-16

Bk 263, p. 75

Found 5/8" ∅ iron on road surface and 2 Co. ties remain, which tied a conc. mon. Ties checked and accepted as a perpetuation of conc. mon.

5/26/05 Fd Pk Nail

7-18-05 SURVEY MARKER SET IN PLACE OF PK NAIL. TIES SET - THIS LOCATION FITS SEC BREAKDOWN INFO FROM BOOK 263 p 75

12-17-86 DRR RMK

