SW Cor SEC. 31-103-16

Cert. Filed 3-11-96 by JHS

4-29-82 JHS CREW Found Conc. Mon. 1' Below Conc. Surface, used Corner on Farmers State Bank Survey, Book-237 pg. 31

12-21-92 JHS CREW Found 3/4" Pipe in Conc. used Corner on Don Angell Survey Book - 377 pg 29

11-15-95 JHS CREW (HLS & JPA) Removed 3/4" Pipe and Set 5/8" x 9" Iron with Cast Iron Mon. over Conc. Mon Found. Cast Iron Mon @ Road Surface.

Mower Co. Records State, Conc. Mon in Place. Inp Iron 3" Down.

11-15-95 Cloudy 35 HLS JPA 35

