S 1/4 COR SEC 33-103-17

1977. BK 194 P 58
JHS CREW FOUND DRILL
HOLE IN CONCRETE SURFACE
3.3' SO OF ℄ OF OLD TH# 16
IN AGREEMENT WITH
TH# 16 R/W MAP.
1996 JHS CREW REPLACED
DRILL HOLE WITH 5/8" Ø
CADDED
DEC 2004 JHS CREW
LOCATED 5/8" Ø & SHOT
WITH GPS

