E¼ cor SEC. 14 - 102 - 17

(50)

MOWER

~~FREEBORN~~ Co. ROAD PLAN

STATES, 3/4" IRON Rod WAS SET

AT S.T.A 26+53.3

JHS CREW CHECKED AREA

AND DID NOT LOCATE IRON

10-26-04

CLOUDY

60°

HLS

MHS

63

