6-13-05
Cloudy
75°
HLS
MHS

SW cor SEC. 21-102-17

No Information Found
in Mower Co. Corner Records

HLS crew Dug with Bobbins
Backhoe on E-W Road
and Location of Spk. .30± Deep.

Dug a 4' x 10' Hole down
to Virgin Soil and Found
No Evidence of PLS corner.

Replaced Spk with
5/8" x 16" Iron with Cast Iron
Cover.

.60± Below Rd.
Surface.

