NE cor SEC. 31-102-17

No Information Found in Mower Co. Corner Records

2002 Mower Co. Dug For corner At Time of Installing New Bridge. No. 50584, And Found Nothing.

JHS crew Dug on ℄ of twprd And in Line with Remains of Line Fence East. Appeared To be 3.5' ± of Fill At this Point. Dug Below Fill Area And Found No Evidence of Pls corner..

Set corner on ℄ twprd And in Line with Field Division East At dist of 2651.0 From E¼ cor SEC. 31 And a Dist. of 0641.50' From E¼ cor: SEC. 30.

(see pg 57)

8-22-02
Cloudy
75°
HLS
SHT

55

