SE. Cor Sec 27-102-17
cert. Filed 5-16-91 by JHs
Dug with Co. backhoe
on ℄ Rd at location
of RR Spk flush on
surface, for bitum.
overlay project
#SAP 30-604-18

Dug a 4'x6'x5' deep
hole and found
at a depth of 3'±
the lower portion
of a harrison clm
cont. digging and
found no further evidence
of PLS Corner or a
perpetuation of. RR
was over clm section
therefore accepted mon.
found and set clm
on road surface
at same location.

5-9-91 DRR RMK

