11-27-95 JHS

S 1/4 COR SEC 31-103-18

Cert. Filed by JHS 10-17-96

F 5/8" RLS 13807

1976, JHS CREW SET THIS COR USING CO 1/16 COR TO NORTH & N 1/4 COR.

JHS CREW DUG WITH BACK HOE & FOUND NO EVIDENCE OF RLS COR, RESET 5/8" IN LOCATION ESTABLISHED IN 1976

BK 237 P21

