✓

SE Cor – Sec. 18-102-18

Bk 263, p. 47

CO. HWY. DEPT. RECORDS INDICATE NO RECORD OF THIS COR. FOUND THAT A LARGE CMP CULVERT HAS BEEN LAID ACROSS N-S TWP. ROAD IN LINE WITH FENCE RUNNING WEST, WHICH WOULD HAVE DESTROYED ORIG. PLS COR. THEREFORE, WE SPLIT ROAD GRADE & SET 5/8" ϕ IRON IN LINE WITH FC. WEST, SINCE THIS IS THE BEST EVIDENCE OF THE LOC. OF THE PLS COR.

SPK & W IN PP NE 43.0

2" ϕ ST. CFP W 45.1

℄ N-S TWP. RD. & FC. WEST

