12-15-99 SJT, CPV

35

NE cor Sec 26-102-18

Fd Pinyon Drill Hole
RESET FROM TIES
PRIOR TO NEW BRIDGE
CONST.

