10-15-91 ✓ 7

N¼ Cor Sec 31-102-18
Cert Filed 1-16-92 by JHS
Dug with Co. backhoe on CL E-W-S roads and uncovered a old road bed 4.5 deep dug a 5'x8'x 7' deep hole and found no evidence of PLS Corner or a perpetuation of. Set CIM on CL

6-16-2003

JHS crew dug 2.5' deep through black top found CIM tipped on side. Reset CIM based on ties.

