E 1/4 Cor Sec 11-103-14
Cert. Filed 11-11-91 by JHS
Dug with Co. backhoe
10'S ℄ of new grade
in line with fence
N-S dug a 5'x 12'x 3'
deep hole and found
3/4"ø x 12" appears a
pipe cut was made
at this location which
destroyed the original
PLS corner or a
perpetuation of.

Accepted 3/4" ø iron as
best evidence and
set CIM

8-14-6 JHS CREW FD 3/4" PIPE 9' S ℄, TIE TO SOUTH FIT, PP & CULV REMEASURED

8-29-91 DRR 5.

