N 1/4 Cor Sec 19 - 103 - 14

7-15-02 JHS crew searched area and found no evidence of PLS corner. Set 5/8" ø capped 13907 at Intersection of E-W-S Fence Lines.

